

Machine receiving process.

SN. 3280320

Indicate if machine has chip conveyor then tag the chip conveyor.

Chip conveyor included.

Indicate if the machine has a coolant pump and how many.

Coolant pump included.

List all tooling.

None

List all work holders.

None Main and Sub

List all collets.

None Main and Sub

Give the number of pucks and mark if any are missing.

Total - 8

Missing - 0

Put all tooling, work holders and pucks in a box and mark. \_\_\_\_\_

List any Sheet metal damage.

None

Make sure all turret plugs are on machine.

Missing - N/A

Check voltage of machine and put a pigtail on accordingly. ✓

Power machine on and state the condition.

Good

Move all axis. Note any concerns.

Good

Run tool changer. Note any concerns.

Good

Run spindles. Note any concerns.

Good

Run parts catcher and conveyor. Note any concerns.

Good

Check all axis backlash readings. Record.

Note any leaking concerns.

None.

Note any other concerns.

Luke Hanes  
Signature

11/12/20  
Date